



ICC Evaluation Service, Inc.
www.icc-es.org

Business/Regional Office ■ 5360 Workman Mill Road, Whittier, California 90601 ■ (562) 699-0543
Regional Office ■ 900 Montclair Road, Suite A, Birmingham, Alabama 35213 ■ (205) 599-9800
Regional Office ■ 4051 West Flossmoor Road, Country Club Hills, Illinois 60478 ■ (708) 799-2305

Legacy report on the 1997 Uniform Building Code™

DIVISION: 07—THERMAL AND MOISTURE PROTECTION
Section: 07310—Shingles

WESTERN RED CEDAR ROOF-COVERING SYSTEM

CLARKE GROUP MARKETING, INC.
33610 EAST BROADWAY AVENUE
MISSION, BRITISH COLUMBIA V2V 4M4
CANADA

AMERICAN ROOFING MATERIALS
33610 EAST BROADWAY AVENUE
MISSION, BRITISH COLUMBIA V2V 4M4
CANADA

GREEN RIVER LOG SALES LTD.
33610 EAST BROADWAY AVENUE
MISSION, BRITISH COLUMBIA V2V 4M4
CANADA

GREEN RIVER LOG SALES LTD.,
HATZIC DIVISION
34980 LOUGHEED HIGHWAY
HATZIC, BRITISH COLUMBIA V2V 4J1
CANADA

MCC CEDAR PRODUCTS
33730 ENTERPRISE AVENUE
ABBOTSFORD, BRITISH COLUMBIA Z2S 4N3
CANADA

PORT HARDY MERCHANDISING
6225 JENSEN COVE ROAD
PORT HARDY, BRITISH COLUMBIA V0N 2P0
CANADA

1.0 SUBJECT

Western Red Cedar Roof-covering Systems.

2.0 DESCRIPTION

2.1 General:

Western red cedar shakes (non-preservative treated) and shingles are manufactured to comply with UBC Standards 15-3 and 15-4, respectively.

2.2 Installation:

Western red cedar shakes (non-preservative treated) and shingles are installed as prescribed in Table 15-B-2 of the 1997 Uniform Building Code™.

2.3 Identification:

Western red cedar shakes (non-preservative-treated) and shingles complying with UBC Standards 15-3 and 15-4 are identified as shown in Figures 1 and 2, respectively. The labels shall include one of the following brand names: Black Hawk, Green River, Scott Cedar or American Roofing Materials.

3.0 EVIDENCE SUBMITTED

Quality control manual and label facsimiles.

4.0 FINDINGS

That the western red cedar shakes (non-preservative treated) and shingles manufactured by the Clarke Group Marketing, Inc., mills listed in this report comply with the 1997 Uniform Building Code™, subject to the following conditions:

- 4.1 The products are identified as noted in this report.
4.2 The products are manufactured by the listees noted in this report, with inspections by Quality Auditing Institute (AA-635).
4.3 The products are installed as stipulated in Section 2.2 of this report.

This report is subject to re-examination in two years.

ICC-ES legacy reports are not to be construed as representing aesthetics or any other attributes not specifically addressed, nor are they to be construed as an endorsement of the subject of the report or a recommendation for its use. There is no warranty by ICC Evaluation Service, Inc., express or implied, as to any finding or other matter in this report, or as to any product covered by the report.






FIGURE 1



FIGURE 2



LEGACY REPORT SUPPLEMENT

ER-5116

Reissued April 1, 2002

ICC Evaluation Service, Inc.
www.icc-es.org

Business/Regional Office ■ 5360 Workman Mill Road, Whittier, California 90601 ■ (562) 699-0543
Regional Office ■ 900 Montclair Road, Suite A, Birmingham, Alabama 35213 ■ (205) 599-9800
Regional Office ■ 4051 West Flossmoor Road, Country Club Hills, Illinois 60478 ■ (708) 799-2305

Legacy report on the 1997 *Uniform Building Code*™

DIVISION: 07—THERMAL AND MOISTURE PROTECTION
Section: 07310—Shingles

WESTERN RED CEDAR ROOF-COVERING SYSTEMS

CLARK GROUP MARKETING, INC.
33610 EAST BROADWAY AVENUE
MISSION, BRITISH COLUMBIA V2V 4M4
CANADA

ISLAND CEDAR PRODUCTS
POST OFFICE BOX 3116
MISSION, BRITISH COLUMBIA V2V 4J3
CANADA

1.0 SUBJECT

Western Red Cedar Roof-covering Systems. (Issued May 1, 2003.)

2.0 DESCRIPTION

No change.

3.0 EVIDENCE SUBMITTED

No change.

4.0 FINDINGS

That the changes noted herein comply with the 1997 *Uniform Building Code*™.

4.1 through 4.3: No change.

Unless specifically noted in this evaluation report supplement, the master report remains valid and unchanged.

This report expires concurrently with the master report dated April 1, 2002.

ICC-ES legacy reports are not to be construed as representing aesthetics or any other attributes not specifically addressed, nor are they to be construed as an endorsement of the subject of the report or a recommendation for its use. There is no warranty by ICC Evaluation Service, Inc., express or implied, as to any finding or other matter in this report, or as to any product covered by the report.

